DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS II130-4 REV. B AND EARLIER AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA130-4 REV.0

REF. TCCA STC: SH18-50 REF. FAA STC: SR04327NY REF. EASA STC: 10069009

1.0 PURPOSE:

It has come to DART's attention that the Liferaft Reservoir Assembly does not install properly with the Reservoir Brackets on the H130 Emergency Float System, P/N 652.2002, S/N VT093997.

The purpose of this service instruction is to provide parts and instructions to shift the Reservoir Brackets aft by 1.0 inch to allow for the Liferaft Reservoir Assembly to install properly. DSI 9831-011 Liferaft Reservoir Bracket Adjustment Kit will be used for the adjustment.

2.0 PROCEDURE:

- 2.1 Install each Reservoir Bracket Assembly, P/N 652.4701 onto an Adjustment Plate, P/N 654.0810 using quantity 2X MS24694C53 Screws, quantity 2X NAS1149C0332R Washers, and quantity 2X MS21043-3 Locknuts.
- 2.2 Remove Forward Floor Panel that has the Plate Doubler installed, from the Aft Baggage Compartment.
- 2.3 Install the modified Reservoir Brackets onto the Plate Doubler and Forward Floor Panel, within the Aft Baggage Compartment, in the location shown in II130-4, Figure 39, using quantity 4X AN3C10A Bolts.
- 2.4 Fit check the Forward Floor Panel. Remove any excess material from the Adjustment Plate if needed. Spot Alodine 1201 any reworked sections per MIL-DTL-5541.
- 2.5 Match drill pilot holes, located on the Adjustment Plate, through the Plate Doubler and Forward Floor Panel using a #30 drill bit.
- 2.6 Install quantity 6X MS20470AD4-10 rivets into the previously drilled holes.
 Note: It is acceptable to upsize or downsize rivets to other MS20470AD4-X or equivalent rivet (customer supplied) to fit the installation.
- 2.7 Reinstall Forward Floor Panel, which now has the Plate Doubler and modified Reservoir Brackets installed.
- 2.8 Install Reservoir Assembly in accordance with II130-4, starting at step 5.2.1.6.
- 2.9 Update aircraft logbook to indicate installation of DSI 9381-011 Liferaft Reservoir Bracket Adjustment Kit.

3.0 PARTS LIST

| F/N | QTY -011 | PART NUMBER | DESCRIPTION | |
|-----|-------------|---------------|---|--|
| | Х | DSI 9831-011 | Liferaft Reservoir Bracket Adjustment Kit | |
| 1 | 2 | 652.4701 | Reservoir Bracket Assembly | |
| 2 | 2 | 654.0810 | Adjustment Plate | |
| 3 | 4 | MS24694C53 | Screw | |
| 4 | 4 | NAS1149C0332R | Washer | |
| 5 | 4 | MS21043-3 | Locknut | |
| 6 | 6 | MS20470AD4-10 | Rivet | |
| 7 | 4 | AN3C10A | Bolt | |
| 8 | 4 | NAS1149C0363 | Washer | |

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01


BY:

D. SHEPHERD (DE # 02)

DATE: 19.07.12
CERT. NO.: SH18-50
ISSUE NO.: 1

| A | NEW ISSUE | | | DM | 19.07.12 |
|---------------|----------------|------|--|-----|--------------|
| REV. | DESCRIPTION BY | | | BY | DATE |
| DESIGN | | DM | DART AEROSPACE LTI | | ID |
| DRAWN | | DM | HAWKESBURY, ONTARIO, CANADA | | |
| CHECKED | | MB | DSI 9831 | | REV. A |
| MFG. APPR. | | N/A | | | SHEET 1 OF 2 |
| APPROVED | | VS , | TITLE | | SCALE |
| DE APPR. | | DS | BRACKET ADJUSTME | ENT | NTS |
| DATE 19.07.12 | | | COPYRIGHT © 2019 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT | | |

WRITTEN PERMISSION FROM DART AEROSPACE LTD



4.0 WEIGHT AND BALANCE:

This DSI has negligible effect on Weight and Balance.

| DESIGN | DM | DART AEROSPACE I | TD | |
|------------|------|---|--------------|--|
| DRAWN | DM | HAWKESBURY, ONTARIO, CANADA | | |
| CHECKED | MB | DRAWING NO. | REV. A | |
| MFG. APPR. | N/A | DSI 9831 | SHEET 2 OF 2 | |
| APPROVED | VS 🔬 | TITLE | SCALE | |
| DE APPR. | DS | BRACKET ADJUSTMENT | NTS | |
| DATE 19.0 | 7.12 | COPYRIGHT © 2019 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD. | | |